



Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Cole Nichols (colen@horizonenvservices.com)
Submission Date: May 21, 2020 10:28:00 AM MDT
Server Receive Date: May 21, 2020 10:31:15 AM MDT
Reference Number: 20200521-18143031788
Location: 557 Airpark Dr, Durango, CO 81303, USA
May 21, 2020 10:30:43 AM MDT [[View Map](#)]

Information

Name: colen@horizonenvservices.com
Date: May 20, 2020
Well Name: JOHNSON, MW GAS UNIT A 2
API Number: 50670656600
Select State: Colorado
Work type: COGCC Inspection AR
Action Complete: Other

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

treated musk thistle

Photo of third corrective action completed



Completed work description of corrective action 3

musk thistle and Russian knapweed goes beyond project boundaries

Photo of fourth corrective action completed



Completed work description

treated musk thistle

Completed work description of corrective action 4

treated noxious weeds in reclamation area

Additional photos



Completed work description

treated noxious weeds in reclamation and along entrance road

Summary of all work completed

previous treatment dates 2016 (on no spray list), 7/10/17, 6/28/18, 6/18/19