

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/27/2020

Submitted Date:

05/27/2020

Document Number:

700700787**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 335007 Ramsey, Scott 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:19 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292140	WELL	PR	08/30/2008	GW	045-14605	SAVAGE 5-13A	SI
292737	WELL	PR	09/14/2009	GW	045-14766	SAVAGE 5-13B	PR
292738	WELL	PR	01/08/2009	GW	045-14765	SAVAGE 5-14D	PR
292739	WELL	PR	10/08/2008	GW	045-14764	SAVAGE 5-14C	PR
292740	WELL	PR	10/08/2008	GW	045-14763	SAVAGE 5-14B	PR
292741	WELL	PR	10/08/2008	GW	045-14762	SAVAGE 5-14A	SI
292742	WELL	PR	08/12/2011	GW	045-14761	SAVAGE 5-13D	SI
292743	WELL	PR	08/01/2019	GW	045-14760	SAVAGE 5-13C	PR
292829	WELL	PR	11/19/2009	GW	045-14795	SAVAGE 5-23A	SI
292830	WELL	PR	08/26/2009	GW	045-14794	SAVAGE 5-23B	SI
292831	WELL	PR	03/01/2017	GW	045-14793	SAVAGE 5-23C	SI
292832	WELL	PR	11/19/2009	GW	045-14792	SAVAGE 5-23-D	SI
292835	WELL	PR	10/08/2008	GW	045-14791	SAVAGE 5-24A	SI
292836	WELL	PR	10/08/2008	GW	045-14789	SAVAGE 5-24C	SI
292837	WELL	SI	02/01/2020	GW	045-14788	SAVAGE 5-24D	PR
292846	WELL	PR	10/08/2008	GW	045-14790	SAVAGE 5-24B	PR

General Comment:

COGCC Inspection Report Summary

On Wednesday 5/27/20 at approximately 11:00 AM, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus 5L, at Location # 335007 in Garfield Colorado.

While there, I observed normal production operations.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒**Signs/Marker:**

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:		Date:	

Type	SEPARATOR			
Comment:				
Corrective Action:			Date:	
Type	WELLHEAD			
Comment:				
Corrective Action:			Date:	

Equipment:

			corrective date
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 16		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 16		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	chemical tank in tank battery		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	1000 GAL	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Inspector Name: Ramsey, Scott

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	8	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities

Facility ID: 292140 Type: WELL API Number: 045-14605 Status: PR Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: shut in at time of inspection

Corrective Action: _____ Date: _____

Facility ID: 292737 Type: WELL API Number: 045-14766 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action: _____ Date: _____

Facility ID: 292738 Type: WELL API Number: 045-14765 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action: _____ Date: _____

Facility ID: 292739 Type: WELL API Number: 045-14764 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action: _____ Date: _____

Facility ID: 292740 Type: WELL API Number: 045-14763 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action: _____ Date: _____

Facility ID: 292741 Type: WELL API Number: 045-14762 Status: PR Insp. Status: SI

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: shut in at time of inspection

Corrective Action: _____ Date: _____

Facility ID: 292742 Type: WELL API Number: 045-14761 Status: PR Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: shut in at time of inspection

Corrective Action: _____ Date: _____

Facility ID: 292743 Type: WELL API Number: 045-14760 Status: PR Insp. Status: PR

Producing Well			
Comment:	<u>producing</u>		
Corrective Action:		Date:	
Facility ID:	<u>292829</u>	Type:	<u>WELL</u>
API Number:	<u>045-14795</u>	Status:	<u>PR</u>
Insp. Status:	<u>SI</u>		
Idle Well			
Purpose:	<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder: _____
Comment:	<u>shut in at time of inspection</u>		
Corrective Action:		Date:	
Facility ID:	<u>292830</u>	Type:	<u>WELL</u>
API Number:	<u>045-14794</u>	Status:	<u>PR</u>
Insp. Status:	<u>SI</u>		
Idle Well			
Purpose:	<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder: _____
Comment:	<u>shut in at time of inspection</u>		
Corrective Action:		Date:	
Facility ID:	<u>292831</u>	Type:	<u>WELL</u>
API Number:	<u>045-14793</u>	Status:	<u>PR</u>
Insp. Status:	<u>SI</u>		
Idle Well			
Purpose:	<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder: _____
Comment:	<u>shut in at time of inspection</u>		
Corrective Action:		Date:	
Facility ID:	<u>292832</u>	Type:	<u>WELL</u>
API Number:	<u>045-14792</u>	Status:	<u>PR</u>
Insp. Status:	<u>SI</u>		
Idle Well			
Purpose:	<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder: _____
Comment:	<u>shut in at time of inspection</u>		
Corrective Action:		Date:	
Facility ID:	<u>292835</u>	Type:	<u>WELL</u>
API Number:	<u>045-14791</u>	Status:	<u>PR</u>
Insp. Status:	<u>SI</u>		
Idle Well			
Purpose:	<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder: _____
Comment:	<u>shut in at time of inspection</u>		
Corrective Action:		Date:	
Facility ID:	<u>292836</u>	Type:	<u>WELL</u>
API Number:	<u>045-14789</u>	Status:	<u>PR</u>
Insp. Status:	<u>SI</u>		
Idle Well			
Purpose:	<input checked="" type="checkbox"/> Shut In	<input type="checkbox"/> Temporarily Abandoned	Reminder: _____
Comment:	<u>shut in at time of inspection</u>		
Corrective Action:		Date:	

Facility ID:	292837	Type:	WELL	API Number:	045-14788	Status:	SI	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	292846	Type:	WELL	API Number:	045-14790	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches		Ditches				
Gravel		Gravel				
Berms		Culverts				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700700792	photos for 5L	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5160132