

Inspection Photos

Location Name: LARAMIE ENERGY LLC Ute Water /22-14 Pad

Location ID: 334539



Network time is not synchronize
Local: May 27, 2020 at 10:50:58 AM MD
+39.2099, -107.771

Photo #1259 from entrance to location



Network time is not synchronize
Local: May 27, 2020 at 10:53:11 AM MD
+39.1438, -108.120

Photo # 1260 Tank label peeling off tank and tank capacity is inaccurate.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Ute Water /22-14 Pad

Location ID: 334539



Photo #1261 Multiple unused bull plugs in tank containment.



Photo #1262 Multiple unused bull plugs in tank containment.