

# Inspection Photos

API: 061-06471

Operator: MARATHON OIL COMPANY

Inspection Date: 5/26/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 061-06471 | Date: 5/26/2020

## Inspection Photos



**Photo 1.** Facing south along the access road. The road has not been reclaimed and is bare of vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06471 | Date: 5/26/2020

## Inspection Photos



**Photo 2.** Facing southwest at the location. There is an elect utility that remains (red arrow) and an abandoned meter shed (yellow arrow). The area is bare of vegetation around the electric utility.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06471 | Date: 5/26/2020



## Inspection Photos



**Photo 3.** Facing back toward the east at the abandoned meter shed that remains at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06471 | Date: 5/26/2020

## Inspection Photos



**Photo 3.** Facing northeast further west of the meter shed (yellow arrow). Pipe risers remain and this area is bare of vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06471 | Date: 5/26/2020