

Inspection Photos

API: 061-06456

Operator: BERRY ENERGY INC

Inspection Date: 5/26/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06456 | Date: 5/26/2020

Inspection Photos



Photo 1. Facing southwest toward the location. The location is mostly bare of vegetation and it does not appear reclamation was performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06456 | Date: 5/26/2020

Inspection Photos



Photo 2. Facing northeast toward the location. The location is mostly bare of vegetation and it does not appear reclamation was performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06456 | Date: 5/26/2020

Inspection Photos



Photo 3. Facing east toward the surrounding undisturbed area which consists of uniform vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06456 | Date: 5/26/2020