

Inspection Photos

API: 061-06397

Operator: BERRY ENERGY INC

Inspection Date: 5/26/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06397 | Date: 5/26/2020

Inspection Photos



Photo 1. Facing south toward the tank battery location. There is a bare area with no vegetation growth approximately 100 ft. x 60 ft.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06397 | Date: 5/26/2020

Inspection Photos



Photo 2. There is a pipe riser that remains at the tank battery location north of the well site at Lat/Long:38.42173,-103.01423.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06397 | Date: 5/26/2020

Inspection Photos



Photo 2. Facing north toward the location. The location is mostly bare of vegetation and it does not appear reclamation was performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06397 | Date: 5/26/2020

Inspection Photos



Photo 3. Facing east toward the surrounding undisturbed area which consists of uniform vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06397 | Date: 5/26/2020