


**Inspection Photos**  
**Location Name: Horsetail 30H PAD**  
**Location ID: 445579**



**Photo 1 – 30H-3116 – Unused Wellheads and sign missing**



**Photo 2 – Wellheads – Signs missing**

