

Inspection Photos
Location Name: Cottonwood 08E-0504
Location ID: 439412



Photo 1 – Belt Driven Unit



Photo 2 – Tank Battery

Inspection Photos
Location Name: Cottonwood 08E-0504
Location ID: 439412



Photo 3 – Unused 400 BBL Crude Oil Tank on the Northside of Location