

Final Reclamation Inspection

May 26, 2020

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 318395

Inspection Document #: 697501566

Weld County, CO

SESW Section 32 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources



Photo 1. Photo taken from the southern access road, facing North. Photo illustrates the Operator attempted to conduct final reclamation activities; however, little to no establishment of desirable plant species was observed throughout much of the access road and well location.

Inspection Photos

Location Name: ROCKY MOUNTAIN FUEL CO

#24-32

Location ID: 318395



Photo 2. Photo taken from a portion of the access road, facing North. See comments under Photo 1.

Inspection Photos

Location Name: ROCKY MOUNTAIN FUEL CO

#24-32

Location ID: 318395



Photo 3. Photo taken from the western well location, facing East. See comments under Photo 1.

Inspection Photos

Location Name: ROCKY MOUNTAIN FUEL CO

#24-32

Location ID: 318395



Photo 4. Photo taken from the southern well location, facing East. See comments under Photo 1.

Inspection Photos

Location Name: ROCKY MOUNTAIN FUEL CO

#24-32

Location ID: 318395



Photo 5. Photo taken from the northern well location, facing East. See comments under Photo 1.