

Inspection Photos

Operator: Highpoint Operating
API#: 033-06144
Date: 5/27/2020




Photo 1. View of the western edge of the well pad facing northward. Vegetation (alfalfa) in left portion of the photo is outside of the project area. Vegetation (largely foxtail grasses) in the right of the photo is within the project area. Vegetation within the project area does not match reference area. Significant areas of bare soil remain. Additional soil remediation is needed for successful revegetation.



Photo 2. View of the project area facing northeastward. Foxtail (*Hordeum jubatum*) grasses do not match reference area comprised of alfalfa crop field.



Photo 3. Another view of failed vegetation within the project area. Crop area is irrigated and only supporting sparse alfalfa that are stunted.



Photo 4. View of the northern project area.




Photo 5. Birdseye view of vegetation on the well pad surface, comprised of foxtail barley (*Hordeum jubatum*), scattered alfalfa plants, and young tamarisk weed.



Photo 6 View of reference area vegetation comprised of irrigated alfalfa field.