

Inspection Photos

Operator: Highpoint Operating
API#: 033-06145
Date: 5/27/2020



Photo 1. View of the western portion of the well pad facing northward. Alfalfa within the project area is significantly more stunted, sparse, and weedy than the alfalfa outside of the project area.



Photo 2. View of representative quadrat vegetation within the project area. Alfalfa is approximately 6 inches tall and sparse. Dandelion, foxtail, and kochia weeds present.



Photo 3. View of another representative quadrat within the project area. Significant areas of bare soil present.



Photo 4. View of another representative quadrat within the project area. In areas where alfalfa is growing it remains sparse and stunted compared to reference area.



Photo 5. View of portion of the former well pad that is not revegetating, facing westward. Several of these “patches” of poor revegetation remain on the former well pad.



Photo 6. View of reference area vegetation comprised of irrigated alfalfa field, with dense alfalfa approximately 24-30 inches tall. Weeds were not observed.



Photo 7 View of reference area vegetation comprised of irrigated alfalfa field.