

Inspection Photos

5/26/2020

Operator: SG INTERESTS I LTD - 77330

Location ID: 324491

Gunnison County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 324491



Photo 1: Photo taken from the south end of the Location, facing west. Photos 1-4 provide an overview of the Location from west, northwest, northeast to east. Photo shows areas on the west end of the Location are not needed for production and have not been reclaimed.



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 324491



Photo 3: See comments under photo 1.



Photo 4: See comments under photo 1. Photo also shows flare equipment: Doc. #400506249 indicated that the flare was to be installed on the west end of the pad, flare appears to have been installed on the southeast corner of the Location.



Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 324491



Photo 5: Photo taken from the southwest end of the Location, facing north. Photo shows areas on the west end of the Location are not needed for production and have not been reclaimed.



Photo 6: Photo taken from the southwest end of the Location, facing northeast. Photo shows areas on the west end of the Location are not needed for production and have not been reclaimed.

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 324491



Photo 7: Photo taken from the north end of the Location, facing east. Photo shows areas where gravel has not been removed (arrow), and vegetation is not achieving uniform vegetative establishment. Vehicle disturbances also observed in these areas.



Photo 8: Photo taken from the north end of the Location, facing south. See comments under photo 1.

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 324491



Photo 9: Photo taken from the northwest end of the Location, facing north. Photo shows areas where Operator appears to be removing soils from slopes on the north end of the Location. Photo also shows vehicle tracking/disturbances.



Photo 10: Photo taken from the north end of the Location, facing east. Photo shows areas where Operator appears to be removing soils from slopes on the north end of the Location.

Inspection Photos
Operator Name: SG INTERESTS I LTD - 77330
Location ID: 324491



Photo 11: Photo taken from the northwest end of the Location, facing southwest. Photo shows vehicle tracking/disturbances and areas where vegetation is not progressing towards uniform establishment.



Photo 12: Photo of the 051-06129. Photo shows containment has filled with fluid and requires maintenance.

