

# Inspection Photos

5/26/2020

Operator: SG INTERESTS I LTD - 77330

Location ID: 324461

Gunnison County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

## Inspection Photos

Operator Name: SG INTERESTS I LTD - 77330

Location ID: 324461



**Photo 1:** Photo taken from the south end of the Location, facing north. Photo shows areas of the Location adjacent to the well where uniform vegetative establishment has occurred.



**Photo 2:** Photo taken from the Location, facing east. Photo shows areas where well was Location; Reclamation in process.

## Inspection Photos

Operator Name: SG INTERESTS I LTD - 77330

Location ID: 324461



**Photo 3:** Photo taken from the Location, facing south. Photo shows access road; Reclamation in process.



**Photo 4:** Photo taken from the access road. Photo shows what appears to be a Musk thistle rosette; Several rosettes were observed along access road. This is a Colorado State Listed noxious weed and requires management.