

Inspection Photos

5/26/2020

Operator: GUNNISON ENERGY LLC - 10515

Location ID: 324457

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324457



Photo 1: Photo taken from the west end of the Location, facing northeast. Photo provides an overview of the Location.



Photo 2: Photo taken from the west end of the Location, facing southeast. Photo provides an overview of the Location.

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324457



Photo 3: Photo taken from the Location. Photo shows vegetation on the Location is predominantly *Taraxacum officinale*; vegetation observed not reflective to that of the reference area, or uniform. Photo also shows gravel/base has not been removed from the Location



Photo 4: Photo taken from the access road. Photo shows what appears to be a Musk thistle rosette; Several rosettes were observed along access road. This is a Colorado State Listed noxious weed and requires management.

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324457



Photo 5: Photo taken from the southwest end of the Location, facing north. Photo shows Reclamation Specialist tested the pad for compaction alleviation compliance; Unable to easily penetrate the soil surface; Compaction concerns evident.



Photo 6: Photo taken from the adjacent reference area. Photo shows Reclamation Specialist tested the soils on the adjacent lands to compare to the compaction concerns observed on the pad; Photo shows Reclamation Specialist was able to soil surface for the entire length of the shovel blade (16 inches).

Inspection Photos

Operator Name: GUNNISON ENERGY LLC - 10515

Location ID: 324457



Photo 7: Photo taken from the southeast end of the pad. Photo shows Musk thistle rosettes; Noxious weed issues observed on Location since 2016. Photo also shows areas where gravel base has not been removed.



Photo 8: Continued from photo 7. Photo shows Musk thistle plant from the 2019 growing season.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location ID: 324457



Photo 9: Photo taken from the access road. Photo shows either Diffuse or Russian Knapweed establishing on Location. Plant observed in photo from 2019 growing season. This is a Colorado State listed Noxious weed and requires management.



Photo 10: Continued from photo 9. Photo shows Knapweed plant growing on Location.