

Inspection Photos
Location Name: Jeanie /AB10-01R Pad
Location #: 430706



Photo #1
Jeanie AB10-01R (05-123-36262) Wellsite
Temporarily Abandoned | TA



Photo #2
Dillard AB 10-08, Jeanie AB10-01R Battery site
Inactive | Shut-down

Inspection Photos
Location Name: Jeanie /AB10-01R Pad
Location #: 430706



Photo #3
Jeanie AB10-01R Wellsite
Stained soil
prior insp.



Photo #4
Jeanie AB10-01R Wellsite
Stained soil : Mitigated

Inspection Photos
Location Name: Jeanie /AB10-01R Pad
Location #: 430706



Photo #5
Jeanie AB10-01R Wellsite
Unused pollution pot
prior insp.



Photo #6
Jeanie AB10-01R Wellsite
Unused pollution pot : Removed

Inspection Photos
Location Name: Jeanie /AB10-01R Pad
Location #: 430706



Photo #7
Jeanie AB10-01R Wellsite
Unused pollution pot
prior insp.



Photo #8
Jeanie AB10-01R Wellsite
Unused pollution pot : Removed

Inspection Photos
Location Name: Jeanie /AB10-01R Pad
Location #: 430706




Photo #9
Jeanie AB10-01R Wellsite
Unused wellhead parts
prior insp.



Photo #10
Jeanie AB10-01R Wellsite
Unused wellhead parts: Removed

Inspection Photos
Location Name: Jeanie /AB10-01R Pad
Location #: 430706



Photo #11
Jeanie AB10-01R Wellsite
Unused tubing
prior insp.



Photo #12
Jeanie AB10-01R Wellsite
Unused tubing: Removed