

Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD UNIT /15-12H2 (D14OU)

Location ID: 334142



Photo #1283 from NW corner of location.



Photo #0872 form inspection #699800812 conducted on 3/30/20.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD UNIT /15-12H2 (D14OU)

Location ID: 334142



Photo #1284 500 gallon methanol tank missing operators name.



Photo #1286 Oily fluid in containment by pigging station.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD UNIT /15-12H2 (D14OU)

Location ID: 334142



Photo #1287 stained gravel in tank containment.



Photo #1288 Stained soil outside of tank containment.