

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/02/2020

Submitted Date:

06/02/2020

Document Number:

696103044

**FIELD INSPECTION FORM**
 Loc ID 428198 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

18 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428193	WELL	PR	07/20/2012	OW	123-35273	Vince State B13-63HN	PR

**General Comment:**

This is a WELL / BATTERY inspection.  
 Well(s): 1: Producing | PR.  
 Battery: Active.

Centralized Battery serves 5 Location IDs (428198, 330538, 330539, 330357, 330358).  
 (Well(s): 1: Producing | PR ; 2: Shut-In | SI ; 2: Temporarily Abandoned | TA).

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:		
Corrective Action:		Date: _____

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Surrounded by metal berms.		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	1 ECD: Iron panel 2 ECDs: None		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 3		
Comment:	ECD scrubbers.		
Corrective Action:		Date:	

Type: Pig Station	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 3		
Comment:	ECD #1, 2: Controls crude oil tanks VOCs. ECD #3: Controls separator VOCs. Pilots: ON.		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	Test / Calibration date: 02/2020.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Centralized Battery serves 5 Location IDs (428198, 330538, 330539, 330357, 330358). (Well(s): 1: Producing   PR ; 2: Shut-In   SI ; 2: Temporarily Abandoned   TA).				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	CONCRETE SUMP/VAULT		,
Comment:					

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	
Other (Content)	
Other (Capacity)	60 Bbls.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: <a href="#">Shares berms w/ crude oil tanks &amp; produced H2O tank &amp; vaults.</a>				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: <a href="#">Shares berms w/ crude oil tanks &amp; produced H2O vaults.</a>				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	53 Bbls.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: <a href="#">Shares berms w/ crude oil tanks &amp; produced H2O tank &amp; vaults.</a>				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
----------	---	----------	------	---------	--------

CRUDE OIL	5	300 BBLs	STEEL AST		40.396340,-104.478730	
Comment: Equalizer lines connects 4 of 5 crude oil tanks.						
Corrective Action:					Date:	
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment: Shares berms w/ produced H2O tank & vaults.						
Corrective Action:					Date:	
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	428193	Type:	WELL	API Number:	123-35273	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing   PR.								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On TUE 06/02/2020 at approximately 15:24 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: NOBLE ENERGY INC  Location Name: Vince State /B13-63HN  Location ID: 428198  Well Name: Vince State B13-63HN  API: 05-123-35273  Location County: Weld County, Colorado  Weather: Partly cloudy, dry.</p> <p>While there, I observed:  Well(s): 1: Producing   PR.  Battery: Active.</p> <p>Centralized Battery serves 5 Location IDs (428198, 330538, 330539, 330357, 330358).  (Well(s): 1: Producing   PR ; 2: Shut-In   SI ; 2: Temporarily Abandoned   TA).</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	06/02/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103045	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164916">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164916</a>