

Inspection Photos

Location Name: LARAMIE ENERGY LLC Jensen /19-01 Pad

Location ID: 426451



Network time is not synchronize
Local: Jun 2, 2020 at 12:49:19 PM MD
+39.2670, -107.803

Photo #1293 from entrance to location



Network time is not synchronize
Local: Jun 2, 2020 at 12:49:51 PM MD
+39.2670, -107.803

Photo #1294 Sediment build up in culvert at entrance to location.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Jensen /19-01 Pad

Location ID: 426451



Network time is not synchronize
Local: Jun 2, 2020 at 12:52:51 PM MD
+39.2677, -107.803



Network time is not synchronize
Local: Jun 2, 2020 at 12:53:19 PM MD
+39.2677, -107.803

Photo #1295 Sediment moving on to location from South West cut slope.

Reeling on South West cut slope.