

Inspection Photos

API: 071-07711

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 5/20/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07711 | Date: 5/20/2020

Inspection Photos



Photo 1. Facing southeast at the beginning of the access road. The cattleguard and road remain with approved variance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07711 | Date: 5/20/2020

Inspection Photos



Photo 2. Facing southeast along the access road. Desirable vegetation is establishing along the road side and the road appears to be stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07711 | Date: 5/20/2020

Inspection Photos



Photo 3. Facing southeast along the access road. There are water bars installed along the road to divert stormwater off the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07711 | Date: 5/20/2020

Inspection Photos



Photo 4. Facing southwest along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07711 | Date: 5/20/2020

Inspection Photos



Photo 5. Facing southeast at the access road. The access road near the location needs to achieve 80% vegetation cover. There are areas along the section of access road which vegetation is well established and other areas shown above that have not yet established 80% vegetation.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07711 | Date: 5/20/2020

Inspection Photos



Photo 6. Facing east toward the location. Desirable vegetation is established well throughout most areas of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07711 | Date: 5/20/2020

Inspection Photos



Photo 7. Facing southeast along the cut slope which is stabilized with vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07711 | Date: 5/20/2020

Inspection Photos



Photo 8. This area at the southeast side of the location approximately 50'x50' which has not established desirable vegetation. This area could use touch up hand seeding.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07711 | Date: 5/20/2020

Inspection Photos



Photo 9. The area along the north/northwest fill slope has not adequately established vegetation and could use touch up hand seeding.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07711 | Date: 5/20/2020

Inspection Photos



Photo 10. Facing south toward the surrounding undisturbed reference vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07711 | Date: 5/20/2020