

Inspection Photos
Location Name: Razor 12H PAD
Location ID: 430096



Photo 1 – Tank Battery



Photo 2 – Compressors and Heater Treaters

Inspection Photos
Location Name: Razor 12H PAD
Location ID: 430096



Photo 3 – 12-0141H – Weeds




Photo 4 – Wellheads – Weeds



Inspection Photos
Location Name: Razor 12H PAD
Location ID: 430096




Photo 3 – 12H-1316B missing Sign – Weeds