



39.86391, -108.99199, 6464.5ft, 277°
06/04/2020 12:38:25 PM



39.86399, -108.99224, 6475.6ft, 358°
06/04/2020 12:39:54 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Tank battery.

Hells Hole 19-1

API: 05-103-10835

Inspection: 700401838



39.86383, -108.99218, 6465.7ft, 357°
06/04/2020 12:38:54 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Tanks, separator, and meter building.

Hells Hole 19-1

API: 05-103-10835

Inspection: 700401838



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Pump jack.

Hells Hole 19-1

API: 05-103-10835

Inspection: 700401838

ROBERT L. BAYLESS, PRODUCER LLC

Hells Hole # 19-1
1067' FNL & 938' FEL
Sec 19, T2S, R103W
Rio Blanco, Colorado
Lease No. COC66378

39.86413, -108.99186, 6462.4ft, 237°

06/04/2020 12:37:07 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Battery sign.

Hells Hole 19-1

API: 05-103-10835

Inspection: 700401838



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Tank label.

Hells Hole 19-1

API: 05-103-10835

Inspection: 700401838



39.8642, -108.99226, 6471.3ft, 172°
06/04/2020 12:41:01 PM



39.86409, -108.99213, 6461.8ft, 286°
06/04/2020 12:51:48 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 9. Weeds next to separator.

Hells Hole 19-1

API: 05-103-10835

Inspection: 700401838





39.86394, -108.99275, 6458 0ft, 195°
06/04/2020 12:43:32 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 11. Oil containers next to pump jack.

Hells Hole 19-1

API: 05-103-10835

Inspection: 700401838



39.864, -108.99255, 6495.4ft, 358°
06/04/2020 12:45:57 PM





COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 14. No well head sign.

Hells Hole 19-1

API: 05-103-10835

Inspection: 700401838





39.86399, -108.99255, 6497.3ft, 329°
06/04/2020 12:45:31 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 16. Tubing gage at 40 psi.

Hells Hole 19-1

API: 05-103-10835

Inspection: 700401838



39.86413, -108.9922, 6475.2ft, 4°
06/04/2020 12:51:05 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 17. Tank hatch open.

Hells Hole 19-1

API: 05-103-10835

Inspection: 700401838



39.864, -108.99283, 6468 4ft, 280°

06/04/2020 12:42:18 PM