

# *Inspection Photos*

*Loc#314170*

*Operator: RMNG/Blk Hills*

*Inspection #:692402253*

*Inspection Date: 5/28/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location.

May 28, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: RMTN NG-BLK Hills Wolf Creek Loc#314170





Photo#2:  
BMPs need seasonal maintenance.



Photo#3:  
BMPs need seasonal maintenance.

May 28, 2020





Photo#4:  
Anchor that needs to be Marked.



Photo#5:  
Exposed line.

May 28, 2020