

Inspection Photos

6/05/2020

Operator: MARALEX RESOURCES INC - 53255

Location ID: 312599

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: MARALEX RESOURCES INC - 53255
Location ID: 312599



Photo 1: Photo taken from the access road, facing north. Photo provides overview of the Location.



Photo 2: Photo taken from the west end of the Location, facing east. Photo provides overview of the Location. Photo also shows previously observed erosion concerns have been repaired and pitting has been installed; Unclear if revegetation activates have been conducted; BMPs appear insufficient to stabilize slopes.

Inspection Photos

Operator Name: MARALEX RESOURCES INC - 53255

Location ID: 312599



Photo 3: Photo taken from the Slopes of the Location; Photo shows erosion degradation (rilling) is recurring.



Photo 4: Photo taken from the Slopes of the Location; Photo shows erosion degradation (rilling) is recurring.