

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/05/2020

Submitted Date:

06/08/2020

Document Number:

696201361

FIELD INSPECTION FORM

 Loc ID 335106 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num:
Operator Information:
 OGCC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: PO BOX 370
 City: PARACHUTE State: CO Zip: 81635
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 2 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335106	LOCATION	AC			-	NAUGLE-66S95W 25NENE	RI

General Comment:

On 6/05/2020, Reclamation Specialist Trujillo conducted an interim reclamation and stormwater inspection at TEP Rocky Mountain's Naugle 66S95w /25NENE location in Garfield County, Colorado.

This inspection is a follow-up to inspection #696201236, and in response to Resolution Form #402408217 regarding the following corrective actions:

603.f: Removal of equipment not needed for the lease by 5/20/2020
 1003: Interim reclamation of areas not needed for production by 7/31/2020

Operator's response within the resolution was that the equipment and disturbed areas on the west end of the Location are not the Operator's. COGCC's response to the resolution was that it is "unclear that the area observed on the west end of the Location was constructed independently from the Location, and not a result of O&G disturbance". Operator was directed within the resolution to provide a Surface Owner Letter.

See Resolution #402408217 for additional information. See the "Reclamation" section of this inspection.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

Inspected Facilities

Facility ID: 335106 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Inspection #696201236 observed areas on the west end of the Location that appeared to be associated O&G disturbance of the Location. Inspection required Operator to comply with Rule 1003.b.

Operator submitted FIRR #402408217 stating areas belonged to the SO and are not under Operator's management. COGCC response in the Resolution stated that a SO letter will need to be provided attached to a Form 4 Sundry, and the CA will remain applicable until the documentation as been provided and sundry approved.

This inspection is to provide an update to the Corrective actions to reflect the resolution.

Corrective Action Provide a Surface Owner letter identifying that the area appearing to be O&G disturbance was not built by an O&G Operator in association with the Naugle-66S95W25NENE Location; that the area has not been or currently utilized for O&G activities, and is under his or her management and responsibility.

CA directing Operator to comply with Rule 1003.b remains applicable until documentation has been provided and sundry approved, or reclamation conducted.

Date **07/31/2020**

Overall Interim Reclamation **Fail**

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation

Well Release on Active Location

Multi-Well Location

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696201362	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5169093