

Inspection Photos

Loc#447695

Operator: Ursa

Inspection Number: 692402243

Inspection Date: 5/27/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location.

May 27, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Ursa BMC B Pad Loc#447695



Photo#2:
Interim Reclamation has been installed.



Photo#3:
Interim Reclamation has been installed

May 27, 2020



Photo#4:
Kochia establishing on newly mulched area.

Photo#5:
Interim Reclamation has been installed

May 27, 2020