

**Inspection Photos**  
**Location Name: Grassy Creek Coal Co 1**  
**Location ID: 316752**



**Photo 1. Overview of location taken facing southwest.**



**Inspection Photos**  
**Location Name: Grassy Creek Coal Co 1**  
**Location ID: 316752**



**Photo 2. Stained soil.**



**Photo 3. Stained soil.**



**Inspection Photos**  
**Location Name: Grassy Creek Coal Co 1**  
**Location ID: 316752**



**Photo 4. Example of rills on access road.**



**Photo 5. Example of rills on access road.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Location Name: Grassy Creek Coal Co 1**  
**Location ID: 316752**



**Photo 6. Example of sediment being transported onto and across access road.**



**Photo 7. Example of sediment leaving access road.**

