



39.82025, -108.2013, 6610.1ft, 280°
06/08/2020 11:16:14 AM



39.8207, -108.20167, 6604.3ft, 238°
06/08/2020 11:17:21 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well head.

ELU 8908A-24 H06 396

API: 05-103-11612

Inspection: 700401879





COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Tanks.

ELU 8908A-24 H06 396 API: 05-103-11612
Inspection: 700401879



39.82044, -108.20195, 6583 4ft, 222°
06/08/2020 11:23:32 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Equipment building.

ELU 8908A-24 H06 396

API: 05-103-11612

Inspection: 700401879



39.82026, -108.20165, 6603 5ft, 292°
06/08/2020 11:26:12 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Emission control device.

ELU 8908A-24 H06 396

API: 05-103-11612

Inspection: 700401879



39.82084, -108.20185, 6603 4ft, 115°
06/08/2020 11:17:36 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 7. Bag by well head.

ELU 8908A-24 H06 396

API: 05-103-11612

Inspection: 700401879





39.82048, -108.20208, 6607.5ft, 108°
06/08/2020 11:22:19 AM









39.82029, -108.2017, 6602.9ft, 341°
06/08/2020 11:25:47 AM



39.82027, -108.20142, 6600.0ft, 69°
06/08/2020 11:26:35 AM




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 14. Unused sign.

ELU 8908A-24 H06 396

API: 05-103-11612

Inspection: 700401879



39.82024, -108.20136, 6594.8ft, 12°
06/08/2020 11:26:51 AM