

Inspection Photos

Loc#335777

Operator: Terra

Inspection Number: 692402279

Inspection Date: 5/27/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location.

May 27, 2020



Photo#2:
Trafficking into paneled Well area.



Photo#3:
Erosion, undercutting of BMPs

May 27, 2020



Photo#4:
Erosion, undercutting of BMPs.



Photo#5:
Erosion, undercutting of BMPs

May 27, 2020




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Terra Federal Loc#335777



Photo#6:
Anchors need maintenance.



Photo#7:
Anchors need maintenance.

May 27, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Terra Federal Loc#335777