

# Final Reclamation Inspection

June 2, 2020

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 336371

Inspection Document #: 697501604

Weld County, CO

SWSW Section 24 T3N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: NESG-63N68W  
Location ID: 336371



**Photo 1.** COGCC COGIS aerial imagery from 2017 illustrates the active multi-well location (orange circle) was a shared tank battery with other PA wells (red circle).

At the time of this inspection, the northern equipment (green circle) no longer remains.

Inspection Photos  
Location Name: NESG-63N68W  
Location ID: 336371



**Photo 2.** Photo taken from the western well location, facing North. Photo illustrates three well have been plugged while two wells remain in TA status.

Inspection Photos  
Location Name: NESG-63N68W  
Location ID: 336371



**Photo 3.** Photo taken from the southern tank battery location, facing North. Photo illustrates equipment remains for the TA wells.

Inspection Photos  
Location Name: NESG-63N68W  
Location ID: 336371



**Photo 4.** Photo taken from the central tank battery location, facing North. Photo illustrates the northern equipment, including a partially buried produced water vessel, has been removed.