

# Inspection Photos

6/9/2020

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 335922

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

**Inspection Photos**  
**Operator Name: CAERUS PICEANCE LLC - 10456**  
**Location ID: 335922**



**Photo 1:** Photo taken from the south end of the Location facing west. Photos 1-4 provide an overview of the Location from west, northwest, northeast to east. Photo shows areas of the Location not necessary for production that have not been reclaimed in accordance with Rule 1003.b



**Photo 2:** See comments under photo 1.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335922



**Photo 3:** See comments under photo 1.



**Photo 4:** See comments under photo 1.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335922



**Photo 5:** Photo taken from the soil stockpile on the east end of the Location, facing west. See comments under photo 1. Photo also shows vegetation on the soil stockpile remains predominantly undesirable weedy plant species such as *Bromus tectorum*. Weeds appear to have reached maturity and are viable; It does not appear that weed management has been performed.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335922



**Photo 6:** Photo taken from the northeast of the pad, facing southwest. Photo shows aerial image of the Location. Photo shows areas of the Location not necessary for production has not been reclaimed in accordance with Rule 1003.b





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335922



**Photo 7:** Photo taken from the southeast t of the pad, facing northwest. Photo shows aerial image of the Location. Photo shows areas of the Location not necessary for production has not been reclaimed in accordance with Rule 1003.b





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335922



**Photo 8:** Photo taken from the south of the pad, facing north. Photo shows aerial image of the Location. Photo shows areas of the Location not necessary for production has not been reclaimed in accordance with Rule 1003.b





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335922




**Photo 9:** Photo taken from the northwest of the pad, facing southeast. Photo shows aerial image of the Location. Photo shows areas of the Location not necessary for production has not been reclaimed in accordance with Rule 1003.b





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335922



**Photo 10:** Photo copied from Doc. #696201149 (Photo #21). Photo shows areas (yellow) that do not appear to be necessary for production activities, and require reclamation in accordance with Rule 1003.b.

