

Final Reclamation Inspection

June 2, 2020

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 424877

Inspection Document #: 697501622

Weld County, CO

NWSW Section 27 T1N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Rael USX #WW27-12
Location ID: 424877



Photo 1. Photo taken from the entrance of location, facing East. Photo illustrates a List B Colorado noxious weed, Scotch thistle.

Inspection Photos
Location Name: Rael USX #WW27-12
Location ID: 424877



Photo 2. Close up photo illustrates a List B Colorado noxious weed, Scotch thistle, starting to flower.

Inspection Photos
Location Name: Rael USX #WW27-12
Location ID: 424877



Photo 3. Photo taken from a portion of the access road, facing East. See comments under Photo 1.

Inspection Photos
Location Name: Rael USX #WW27-12
Location ID: 424877



Photo 4. Photo taken from western well location, facing Southeast. See comments under Photo 1.

Inspection Photos
Location Name: Rael USX #WW27-12
Location ID: 424877



Photo 5. Photo taken from western well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: Rael USX #WW27-12
Location ID: 424877



Photo 6. Photo taken from western well location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: Rael USX #WW27-12
Location ID: 424877



Photo 7. Photo taken from southern well location. Photo illustrates a native thistle, Wavyleaf thistle, that does not need to be controlled or managed.