

Final Reclamation Inspection

June 2, 2020

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 424495

Inspection Document #: 697501623

Weld County, CO

NWNW Section 27 T1N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: RITCHEY USX # WW27-04
Location ID: 424495



Photo 1. Photo taken from the southern tank battery location, facing South. Photo illustrates a List B Colorado noxious weed, Scotch thistle.

Inspection Photos

Location Name: RITCHEY USX # WW27-04

Location ID: 424495



Photo 2. Photo taken from the southern tank battery location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: RITCHEY USX # WW27-04
Location ID: 424495



Photo 3. Photo taken from the tank battery location, facing West. Photo illustrates equipment that remains.