

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402392933

Receive Date:

05/12/2020

Report taken by:

John Heil

Site Investigation and Remediation Workplan (Initial Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: <u>LOCIN OIL CORPORATION</u>	Operator No: <u>51130</u>	Phone Numbers
Address: <u>2445 TECHNOLOGY FOREST BD #710</u>		Phone: <u>(281) 362-8600</u>
City: <u>THE WOODLANDS</u>	State: <u>TX</u> Zip: <u>77381</u>	Mobile: <u>(832) 257-7373</u>
Contact Person: <u>Michael Nicol</u>	Email: <u>mnicol@locinoil.com</u>	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 15641Initial Form 27 Document #: 402392933

PURPOSE INFORMATION

- | | |
|--|--|
| <input type="checkbox"/> 901.e. Sensitive Area Determination | <input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water |
| <input checked="" type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation | <input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste | <input type="checkbox"/> Rule 906.c.: Director request |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input type="checkbox"/> Other _____ |

SITE INFORMATION

N Multiple Facilities (in accordance with Rule 909.c.)

Facility Type: <u>PIT</u>	Facility ID: <u>103995</u>	API #: _____	County Name: <u>RIO BLANCO</u>
Facility Name: <u>Fork Unit 9-10-2-2</u>		Latitude: <u>39.886779</u>	Longitude: <u>-108.822342</u>
		** correct Lat/Long if needed: Latitude: <u>39.886575</u>	Longitude: <u>-108.821815</u>
QtrQtr: <u>NESE</u>	Sec: <u>10</u>	Twp: <u>2S</u>	Range: <u>102W</u> Meridian: <u>6</u> Sensitive Area? <u>No</u>

SITE CONDITIONS

General soil type - USCS Classifications OHMost Sensitive Adjacent Land Use RangelandIs domestic water well within 1/4 mile? NoIs surface water within 1/4 mile? NoIs groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

Two dry ephemeral drainages are present, one at approximately 1,675 feet to the east and the other is approximately 1,775 feet to the west.

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- ☒ E&P Waste ☐ Other E&P Waste ☐ Non-E&P Waste
- ☒ Produced Water ☐ Workover Fluids
- ☐ Oil ☐ Tank Bottoms
- ☐ Condensate ☐ Pigging Waste
- ☐ Drilling Fluids ☐ Rig Wash
- ☐ Drill Cuttings ☐ Spent Filters
- ☐ Pit Bottoms
- ☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	SOILS	TBD	Field Screening and Analytical Data

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

As the pit was backfilled during P&A work in 2019, Initial actions will consist of site delineation via hand auguring to a depth of 5 feet below the surface of the pit footprint and side walls. Soil samples will be collected in one (1) foot intervals and field screened using a Photo-Ionizing Detection (PID) unit and a Petroflag. A grab sample will be submitted from the pit bottom interval with the highest field screening result for full COGCC Table 910-1. Additional samples collected from the pit side walls will be submitted to the lab from the interval that contains the highest field screening reading.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Five soil samples will be collected from the pit bottom and side walls. Locin is requesting a reduced analyte list to consist of the TPH (DRO & GRO) and BTEX for the side walls if the sample from the pit bottom sample does not exceed Metals/PAH, as well as inorganics as samples will be collected at a depth greater than 3ft, allowing for consideration request as per COGCC FAQ 32.

Proposed Groundwater Sampling

☐ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 5

Number of soil samples exceeding 910-1 0

Was the areal and vertical extent of soil contamination delineated?

Approximate areal extent (square feet) 0

NA / ND

-- Highest concentration of TPH (mg/kg) 0

-- Highest concentration of SAR 0

BTEX > 910-1

Vertical Extent > 910-1 (in feet) 0

Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet)

Number of groundwater monitoring wells installed

Number of groundwater samples exceeding 910-1

Highest concentration of Benzene (µg/l)

Highest concentration of Toluene (µg/l)

Highest concentration of Ethylbenzene (µg/l)

Highest concentration of Xylene (µg/l)

Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected

0 Number of surface water samples exceeding 910-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☐ Is further site investigation required?

REMEDIAL ACTION PLAN

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

It is unknown if impacted soils are present at this time. The pit has been backfilled during P&A activities in 2019, removing the source.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

If it is determined that soils exceed COGCC Table 910-1 thresholds, they will be excavated via backhoe/trackhoe and stockpiled onsite for further evaluation. Once field screening results indicate that all impacted soils have been excavated and soils satisfy COGCC Table 910-1 thresholds, additional confirmation samples will be collected from within the pit. Confirmation samples will consist of one final full COGCC Table 910-1 sample collected from the bottom. Confirmation samples from side walls will be collected if initial sampling and analysis indicated exceedances. The side walls will be analyzed for only the exceedances noted in the initial sampling.

Soil Remediation Summary

☐ In Situ

_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Air sparge / Soil vapor extraction
_____ Natural Attenuation
_____ Other _____

☐ Ex Situ

_____ Excavate and offsite disposal
_____ If Yes: Estimated Volume (Cubic Yards) _____
_____ Name of Licensed Disposal Facility or COGCC Facility ID # _____
_____ Excavate and onsite remediation
_____ Land Treatment
_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Other _____

Groundwater Remediation Summary

No _____ Bioremediation (or enhanced bioremediation)
No _____ Chemical oxidation
No _____ Air sparge / Soil vapor extraction
No _____ Natural Attenuation
No _____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater impacts are not expected at this time.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: ☐ Quarterly ☐ Semi-Annually ☐ Annually ☐ Other _____

Report Type: ☐ Groundwater Monitoring ☐ Land Treatment Progress Report ☐ O&M Report

☐ Other _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? _____

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The pit will be reclaimed to the present grade of the location or to the approximate original contour of the landscape and consistent with the 1000-series Rule.

Seeding of the disturbed area will be performed in accordance with its' intended use. The seed mix will be prescribed by the landowner. There are no known noxious weeds in the immediate area of the disturbance.

Is the described reclamation complete? ☐ No _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim? ☐ Final?

Did the Surface Owner approve the seed mix? ☐ Yes _____

If NO, does the seed mix comply with local soil conservation district recommendations? ☐ Yes _____

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, if known. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 06/01/2020

Date of commencement of Site Investigation. _____

Date of completion of Site Investigation. _____

REMEDIAL ACTION DATES

Date of commencement of Remediation. _____

Date of completion of Remediation. _____

SITE RECLAMATION DATES

Date of commencement of Reclamation. _____

Date of completion of Reclamation. _____

OPERATOR COMMENT

Information within this Initial Form 27 is to outline the site investigation and delineation procedures necessary to closure the earthen blown down pit and to obtain a remediation number (REM#). Should initial sampling results indicate that soils satisfy COGCC Table 910-1 thresholds, a Supplemental Form 27 will be submitted, requested closure. Should soils exceed Table 910-1, a Supplemental Form 19 will be submitted outlining the proposed remediation actions.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Michael Nicol

Title: Manager

Submit Date: 05/12/2020

Email: mnicol@locinoil.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: John Heil

Date: 06/17/2020

Remediation Project Number: 15641

COA Type**Description**

	Operator shall provide 72 hours notice to Environmental staff John Heil (john.heil@state.co.us) or 970-787-0029 prior to conducting field operations related to closing this pit.
	The operator shall comply with Rule 910.b.3. The operator shall ensure that analytical laboratories use appropriate methods with detection limits less than or equal to the concentrations in Table 910-1.
	This Site Investigation and Remediation Workplan (Form 27) is conditionally approved; however, additional information or activities may be required during the course of remediation.
	COGCC EPS staff should be notified immediately, in the event that groundwater is encountered during investigation
	Surface disturbances shall be reclaimed in accordance with the 1000 Series Reclamation Regulations. Consult COGCC Reclamation Specialist regarding interim and/or final reclamation.

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

402392933	FORM 27-INITIAL-SUBMITTED
402392945	SOIL SAMPLE LOCATION MAP

Total Attach: 2 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)