





40.11889, -108.78987, 5388.0ft, 277°

06/17/2020 12:10:17 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Government 1041 Tk. Battery Location id: 446566
Inspection: 700402001



40.11888, -108.78987, 5384.9ft, 266°
06/17/2020 12:10:47 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Produced water tanks & pump building.

Government 1041 Tk. Battery Location id: 446566
Inspection: 700402001



40.11927, -108.79033, 5391.0ft, 27°
06/17/2020 12:12:38 PM



40.11934, -108.79042, 5383.4ft, 27°
06/17/2020 12:15:13 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Well headers.

Government 1041 Tk. Battery Location id: 446566
Inspection: 700402001



40.11922, -108.79041, 5385.7ft, 316°
06/17/2020 12:22:57 PM





40.11928, -108.79048, 5382.0ft, 346°
06/17/2020 12:17:30 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 9. North treater.

Government 1041 Tk. Battery Location id: 446566
Inspection: 700402001



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 10. North treater.

Government 1041 Tk. Battery Location id: 446566
Inspection: 700402001



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 11. North treater.

Government 1041 Tk. Battery Location id: 446566
Inspection: 700402001



40.11935, -108.79041, 5381.8ft, 284°
06/17/2020 12:13:36 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 13. Stained soil by treaters.

Government 1041 Tk. Battery Location id: 446566
Inspection: 700402001

