

Inspection Photos  
Location Name: Windsor LV2 14-M Pad  
Location ID: 449441



Photo 1: Tank Battery Sign



Photo 2: Tank Battery



Inspection Photos  
Location Name: Windsor LV2 14-M Pad  
Location ID: 449441



Photo 3: Equipment removed



Photo 4: Barrel removed, unused riser, stained soil





**Inspection Photos**  
**Location Name: Windsor LV2 14-M Pad**  
**Location ID: 449441**



**Photo 5: Riser in use**



**Photo 6: Debris removed**



Inspection Photos  
Location Name: Windsor LV2 14-M Pad  
Location ID: 449441



Photo 7: Trash



Photo 8: Wellhead Sign





**Inspection Photos**  
**Location Name: Windsor LV2 14-M Pad**  
**Location ID: 449441**



**Photo 9: Wellhead**



**Photo 10: Stained soil**



Inspection Photos  
Location Name: Windsor LV2 14-M Pad  
Location ID: 449441



Photo 11: Wellhead Sign




Photo 12: Wellhead





**Inspection Photos**  
**Location Name: Windsor LV2 14-M Pad**  
**Location ID: 449441**



Colorado Oil and Gas Conservation Commission  
40.48195, -104.85243, 1447.0m, 2°  
Jun 17, 2020 12:00:27

**Photo 13: Stained soil**