

Inspection Photos
Location Name: Hondke 4
Location ID: 428424



Photo #1 Tanks.

Photo #2 Separators.

Inspection Photos
Location Name: Hondke 4
Location ID: 428424



Photo #3 Pump Jack.

Photo #4 Chemical barrels.

Inspection Photos
Location Name: Hondke 4
Location ID: 428424



Photo #5 Stained soil under separator.

Photo #6 stained soil between crude tanks.

Inspection Photos
Location Name: Hondke 4
Location ID: 428424



Photo #7 Stained soil next to crude tank

Photo #8 Stained soil around load off bucket.

Inspection Photos
Location Name: Hondke 4
Location ID: 428424



Photo #9 load off bucket full and no bull plug.



Photo #10 stained soil and no bull plug in crude tank