

Inspection Photos
Location Name: Lost Creek #45
Location ID: 310792



Photo 1 – Tank Battery




Photo 2 – Wellhead, weeds



Inspection Photos
Location Name: Lost Creek #45
Location ID: 310792



Photo 3 – East Side of Tank



Photo 4 – Plug/Fitting leaking down the side of tank to ground



Inspection Photos
Location Name: Lost Creek #45
Location ID: 310792




Photo 5 – Stained Soil



Photo 6 – Low Berms, Weeds



Inspection Photos
Location Name: Lost Creek #45
Location ID: 310792




Photo 7 – Low Berms, Weeds



Photo 8 – Weeds at Separator