

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/16/2020

Submitted Date:

06/17/2020

Document Number:

689501067**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Oakman, Kari 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
463367	SPILL OR RELEASE	AC			-	Eugene Doversberger #2 2	EI

General Comment:[COGCC Environmental Inspection of Spill ID 463367 and Remediation Project No. 13051.](#)[Any corrective actions from previous inspections that have not been addressed are still applicable.](#)

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: COGCC Environmental Inspection of Spill ID 463367 and Remediation Project No. 13051. Soil excavation at this location has been backfilled and remediation complete. Form 27 Initial (doc # 401988540) documents the successful clean-up of this spill/remediation project.

Corrective Action: Spill ID 463367 and Remediation Project No. 13051 remain open at this location. Submit a Supplemental Form 19 requesting closure of Spill ID 463367, referencing Remediation Project No. 13051. Submit a Supplemental Form 27 requesting closure of this remediation project.

Date: 07/16/2020

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402424645	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5177763
689501068	Site photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5177751