

Inspection Photos  
Location Name: Eleanor Arnold B  
Location ID: 320084



Photo #1 Crude tank.



Photo #2 Produced water open top tank.

Inspection Photos  
Location Name: Eleanor Arnold B  
Location ID: 320084



Photo #3 Separator & Meter.

Photo #4 Well head.

Inspection Photos  
Location Name: Eleanor Arnold B  
Location ID: 320084



Photo #5 Stained soil under load off line of Crude tank.

Photo #6 gaps in chicken wire over produced water tank.

**Inspection Photos**  
**Location Name: Eleanor Arnold B**  
**Location ID: 320084**



**Photo #7 Stained soil at well head.**