

Inspection Photos

6/24/2020

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 312618

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312618



Photo 1: Photo shows the starting point for the 1st disturbance area transect, facing northeast.




Photo 2: Photo taken from the 50th point of the 1st disturbance area transect, facing northwest.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312618



Photo 3: Photo taken from the 50th point of the 1st disturbance area transect, facing southeast.




Photo 4: Photo taken from the 50th point of the 1st disturbance area transect.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312618



Photo 5: Photo shows the ending point for the 1st disturbance area transect, facing southwest.



Photo 6: Photo shows the starting point for the 2nd disturbance area transect, facing northeast.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312618



Photo 7: Photo taken from the 50th point of the 2nd disturbance area transect, facing northwest.



Photo 8: Photo taken from the 50th point of the 2nd disturbance area transect, facing southeast.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312618



Photo 9: Photo taken from the 50th point of the 2nd disturbance area transect.



Photo 10: Photo shows the ending point for the 2nd disturbance area transect, facing southwest.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312618



Photo 11: Photo shows the starting point for the **reference area** transect, facing north.



Photo 12: Photo taken from the 50th point of **reference area** transect, facing east.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312618



Photo 13: Photo taken from the 50th point of **reference area** transect, facing west.



Photo 14: Photo taken from the 50th point of **reference area** transect.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312618



Photo 15: Photo shows the end point for the **reference area** transect, facing south.

