

Inspection Photos
Location Name: Lost Creek #8
Location ID: 332212



Photo 1 – Tank Battery, Weeds



Photo 2 – Wellhead, Weeds



Inspection Photos
Location Name: Lost Creek #8
Location ID: 332212



Photo 3 – Produced Water missing Content, Capacity, NFPA Labels, Weeds




Photo 4 – Crude Oil missing Content Label, Weeds

Inspection Photos
Location Name: Lost Creek #8
Location ID: 332212



Photo 5 – Separator, Weeds



Photo 6 – Wellhead Sign

