

Inspection Photos
Location Name: Lost Creek #23
Location ID: 305139




Photo 1 – Tank Battery, Weeds. Crude Oil Tank missing Content Label

Photo 2 – Wellhead, Weeds, Stained Soil

Inspection Photos
Location Name: Lost Creek #23
Location ID: 305139



Photo 3 – Stained Soil North of Wellhead, Weeds



Photo 4 – Trash, Weeds. Tank missing Content and NFPA Labels

Inspection Photos
Location Name: Lost Creek #23
Location ID: 305139




Photo 5 – Stained Soil at Crude Oil Tank

Photo 6 – Stained Soil at Drain Valve

Inspection Photos
Location Name: Lost Creek #23
Location ID: 305139



Photo 7 – Tank Battery Sign

Photo 8 – Separator and Produced Water Tank, Weeds.