

Inspection Photos
Location Name: Okes 5-6
Location ID: 313043



Photo 1. Overview of location taken facing northeast.



Photo 2. Stained soil from apparent spill.

Inspection Photos
Location Name: Okes 5-6
Location ID: 313043



Photo 3. Stained soil from apparent spill.



Photo 4. Stained soil from apparent spill.

Inspection Photos
Location Name: Okes 5-6
Location ID: 313043



Photo 5. Hole in tank.



Photo 6. Close up of hole from photo 5.

Inspection Photos
Location Name: Okes 5-6
Location ID: 313043



Photo 7. Hole in base of tank with water visible.



Photo 8. Close up of hole and water from photo 7.

