

Inspection Photos
Location Name: Visintainer Federal 1-12
Location ID: 313133



Photo 1. Overview of location taken facing southwest.



Inspection Photos
Location Name: Visintainer Federal 1-12
Location ID: 313133



Photo 2. Separator stored on location.



Photo 3. Noxious weeds on location.

