



Inspection Photos

Location 324625

Pit 11693

Remediation Project 11542

Inspection Date: 6/24/2020

All Photos taken by Kris Neidel

Photo #1 Sign on Pumpjack.



Inspection Photos

Location 324625

Pit 11693

Remediation Project 11542

Inspection Date: 6/24/2020

All Photos taken by Kris Neidel



Photo #2 wellhead cut. Document review shows the well was indented to be PA on 8/12/2019



Inspection Photos

Location 324625

Pit 11693

Remediation Project 11542

Inspection Date: 6/24/2020

All Photos taken by Kris Neidel



Photo #3 shows stockpiled soil pile. Note no wellhead marker at old wellhead.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location 324625

Pit 11693

Remediation Project 11542

Inspection Date: 6/24/2020

All Photos taken by Kris Neidel



Photo #4 stockpiled soil at old treater.





Inspection Photos
Location 324625
Pit 11693
Remediation Project 11542
Inspection Date: 6/24/2020
All Photos taken by Kris Neidel

Photo #5 back to camera is wellhead, camera is facing
Northeast. Road in background is County Rd 26B



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
Location 324625
Pit 11693
Remediation Project 11542
Inspection Date: 6/24/2020
All Photos taken by Kris Neidel

Photo #6 Treater. Note southern end of excavation.



Inspection Photos

Location 324625

Pit 11693

Remediation Project 11542

Inspection Date: 6/24/2020

All Photos taken by Kris Neidel



Photo #7 Photo taken looking north, standing at the south end of excavation.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location 324625

Pit 11693

Remediation Project 11542

Inspection Date: 6/24/2020

All Photos taken by Kris Neidel



Photo #8 Photo taken standing on west side of excavation, looking east.

Inspection Photos

Location 324625

Pit 11693

Remediation Project 11542

Inspection Date: 6/24/2020

All Photos taken by Kris Neidel



Photo #9 looking northeast. Excavation was the area of old pit and tin horn separator, is now filled with water. No obvious sign of oil (rainbows) were observed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location 324625

Pit 11693

Remediation Project 11542

Inspection Date: 6/24/2020

All Photos taken by Kris Neidel



Photo #10 Photo taken looking west. Pumpjack and drive motor still present on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location 324625

Pit 11693

Remediation Project 11542

Inspection Date: 6/24/2020

All Photos taken by Kris Neidel



Photo #11 Looking east



Inspection Photos

Location 324625

Pit 11693

Remediation Project 11542

Inspection Date: 6/24/2020

All Photos taken by Kris Neidel



Photo #12 2-Above ground tanks present at location.



Inspection Photos

Location 324625

Pit 11693

Remediation Project 11542

Inspection Date: 6/24/2020

All Photos taken by Kris Neidel



Photo #13 depression in the ground near the northern tank.
What is this?



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location 324625

Pit 11693

Remediation Project 11542

Inspection Date: 6/24/2020

All Photos taken by Kris Neidel



Photo #14 Looking south at the west side of tanks.



Inspection Photos

Location 324625

Pit 11693

Remediation Project 11542

Inspection Date: 6/24/2020

All Photos taken by Kris Neidel



Photo #15 Photo taken from County Rd 26B, sign at entrance to location.



Inspection Photos

Location 324625

Pit 11693

Remediation Project 11542

Inspection Date: 6/24/2020

All Photos taken by Kris Neidel



Photo #16 Looking at pad from county rd 26B. The pad is elevated above the county road.





Inspection Photos
Location 324625
Pit 11693
Remediation Project 11542
Inspection Date: 6/24/2020
All Photos taken by Kris Neidel

Photo #17 photo of the pad from county rd.



Inspection Photos

Location 324625

Pit 11693

Remediation Project 11542

Inspection Date: 6/24/2020

All Photos taken by Kris Neidel



Photo #18 north side of excavation from road.



Inspection Photos

Location 324625

Pit 11693

Remediation Project 11542

Inspection Date: 6/24/2020

All Photos taken by Kris Neidel



Photo #19 bare dirt is the path of previous spills observed. It appears that no vegetative growth is occurring.

