

Inspection Photos
Location Name: Southern Ute A 5-1
Spill/Release Point ID: 477070



Spill/Release Point ID #477070 location photo.



Spill/Release Point ID #477070

Inspection Photos
Location Name: Southern Ute A 5-1
Spill/Release Point ID: 477070



Proximity to irrigation ditch.



Spill/Release point partially filled with fluid.

Inspection Photos
Location Name: Southern Ute A 5-1
Spill/Release Point ID: 477070



Flow path to the west of the release point, leading into adjacent irrigation ditch.



Flow path from release point.

Inspection Photos
Location Name: Southern Ute A 5-1
Spill/Release Point ID: 477070



No visual impacts to irrigation ditch observed during this inspection.



No sheen or discoloration observed within the waterway.