

Inspection Photos

Location Name: Federal 68S101W 9SESW Pad

Location ID: #324392

Inspection Date: June 19, 2020



Photo #1 – Well sign.



Photo #2 – View of tank battery from southwest. Note: berm is eroded.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Federal 68S101W 9SESW Pad

Location ID: #324392

Inspection Date: June 19, 2020



Photo #3 – View of tank from southeast. Note: berm is eroded.



Photo #4 – View of pad from south. Note: berm is eroded.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources