

Inspection Photos

Location Name: Government 68S101W 8NESE Pad

Location ID: #323860

Inspection Date: June 19, 2020



Photo #1 – Well sign.



Photo #2 –Overview of pad, from east.



Inspection Photos

Location Name: Government 68S101W 8NESE Pad

Location ID: #323860

Inspection Date: June 19, 2020



Photo #3 – Localized accumulation of oil-stained soil at wellhead.



Photo #4 – Unused pump jack on west side of pad.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources