

Inspection Photos
Operator: BP America
API: 067-07201
Date: 6/29/2020



Photo 1. View of area where fluids are being released on the well pad.



Photo 2. Downstream view of fluid release on the well pad toward the western edge.



Photo 3. View of location where active release is emerging from the ground.



Photo 4. View of the southern project area from the southwestern corner facing eastward. Straw mulch placed on the well pad. It appears revegetation is conducted in the interim reclamation area.



Photo 5. View of the well pad from the southwestern corner facing center.



Photo 6. View of the reference area, comprised of irrigated grass field.