

Interim Reclamation Inspection

June 22, 2020

Operator: NOBLE ENERGY INC - #100322

Location ID: 425062

Inspection Document #: 697501685

Weld County, CO

NWNE Section 8 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources



Photo 1. Photo taken from the wellhead, facing North. Photo illustrates the well appears to currently be in temporarily abandoned status, as did well 123-34263. The associated offsite tank battery, in the background, is located to the north ~150'. There were no reclamation issues observed at this well location or the tank battery.



Photo 2. Photo taken from the wellhead. See comments under Photo 1.



Photo 3. Photo taken from the wellhead. See comments under Photo 1.